




NO.S004 Feeder Window Piping and Cabling Position Diagram



Key installation technical points and precautions
1. Use a special wrench to tighten the end connector at the feeder window.



No.	Installation Procedure				Acceptance Criteria		Special Tool	
1	Use a special wrench to tighten the end connector at the feeder window.				-		-	
3	-	-	DKBA68642353	M60 end connector wrench	103*120*308	1	pcs	
2	-	-	DKBA68630853	M50 end connector wrench	89.5*120*308	1	pcs	
1	-	-	DKBA68630852	M25 end connector wrench	58.5*120*308	1	pcs	
No.	BOM Code	Container No.	Drawing No.	Name	Specifications	Quantity	Unit	

REVISIONS		
NO.	DESCRIPTION	DATE
NOTE:		
PROJECT		
DRAWING TITLE		
CHECKED BY /DATE		
DRAWN BY /DATE		
DESIGNED BY /DATE		
CLIENT		
SCALE		STATUS
DATE		DRAWING NO.